

Individually Priced Repairs for Mobile Scanners

Eco Rate for common repairs, and Cap on severely damaged units.



	Price
For example, if device only requires Touch-Screen Replacement, your repair cost is \$45. Instead of the higher old flat rate price (usually \$150-\$350), you are only paying \$45.	
Windows Device Touch-Screen Replacement	\$45.00
Android Device Touch-Screen Replacement	\$55.00 - \$195.00
Trigger Replacement / Repair	\$45.00
Scanner Exit Window Replacement	\$30.00
Speaker Replacement	\$45.00
Internal Backup Battery Replacement	\$30.00
Color LCD Display Replacement (Dependant on Model - Please Email your part number to confirm device's LCD replacement cost)	\$75.00 - \$195.00
Keypad Repair / Replacement	\$95.00
Top Shell Replacement	\$95.00
Bottom Shell Replacement	\$95.00
Keyboard Ribbon-Flex Replacement	\$50.00
Scan Engine Ribbon Flex Replacement	\$45.00
Scan Engine Replacement (Dependant on Model - Please Email your part number to confirm device's Scan Engine replacement cost)	\$45.00 - \$195.00
LCD Display Ribbon Flex Replacement	\$45.00
Battery Pins Repair / Replacement	\$75.00
Bottom Communication Connector Repair / Replacement	\$75.00
CPU Mainboard replacement (Dependant on Model Series - Please Email your part number to confirm CPU replacement cost)	\$100.00 - \$995.00
<u>All Repairs include</u> - Turnaround 3-10 working days in shop, 100 Day Warranty on repairs performed.	
Repair Cap-Off - not to exceed \$275.00 for any device requiring multiple repairs to fix. CPU MainBoard failure/replacement is the only part NOT covered by the Cap)	\$275.00

Bottomline: no contract, no pre-payment, no minimum. You pay for the repair you require at a reasonable pre-determined rate.